






# BASEMENT FLOOR

-  = ELEVATOR
-  = STAIRS
-  = HANDICAP RESTROOM
-  = MENS
-  = WOMENS
-  = MEN/WOMENS







-  = ELEVATOR
-  = STAIRS
-  = HANDICAP RESTROOM
-  = MENS
-  = WOMENS
-  = MEN/WOMENS




# SECOND FLOOR




-  = ELEVATOR
-  = STAIRS
-  = HANDICAP RESTROOM
-  = MENS
-  = WOMENS
-  = MEN/WOMENS




# THIRD FLOOR




-  = ELEVATOR
-  = STAIRS
-  = HANDICAP RESTROOM
-  = MENS
-  = WOMENS
-  = MEN/WOMENS




# FOURTH FLOOR



-  = ELEVATOR
-  = STAIRS
-  = HANDICAP RESTROOM
-  = MENS
-  = WOMENS
-  = MEN/WOMENS





# FIFTH FLOOR




# BUILDING 6M FIRST FLOOR

-  = LOBBY
-  = PHARMASIST
-  = HANDICAP RESTROOM
-  = MENS
-  = WOMENS
-  = MEN/WOMENS





-  = PAIN MANAGEMENT & ACUPUNCTURE CHECK IN
-  = C & P CHECK IN
-  = AUDIOLOGY CHECK IN
-  = LOW VISION & VIST CHECK IN
-  = HANDICAP RESTROOM
-  = MENS
-  = WOMENS
-  = MEN/WOMENS



# BUILDING 7M FIRST FLOOR